



# Technical Service Bulletin

**Cobra Moto, LLC**

240 Uran Street  
Hillsdale, Michigan 49242

(517) 437-9100 phone  
(517) 437-9101 fax

December 16, 2016

## Bearing Retainers in 50 Engines TSB1217

Cobra is no longer installing bearing retainers in the engine cases of the 50cc engine. On the inside of the clutch side engine case it is noticeable that the holes have been drilled but they have not been tapped.

