



Technical Service Bulletin

Cobra Moto, LLC

240 Uran Street
Hillsdale, Michigan 49242

(517) 437-9100 phone
(517) 437-9101 fax

September 16, 2016

2016 CX50 FWE Cylinders TSB00117

The cylinder with machined exhaust port for the 2016 Factory Works Edition CX50 has been replaced by the 2017 CX50 King cylinder which has no machining done to them. They perform identically on the dyno.

The part number remains ECMU0261

Pictures of each are below.

