



Technical Service Bulletin

Cobra Moto, LLC

240 Uran Street
Hillsdale, Michigan 49242

(517) 437-9100 phone
(517) 437-9101 fax

January 4, 2018

Piston Kits for CX50 for Venom Engine TSB0518

Cobra is releasing new pistons for the CX50 Venom Engine. The new piston does not have the two oiling holes on the exhaust side. This will impact

- 2016 – FWE
- 2017 – P3, JR, King & FWE
- 2018 – P3, JR, King & FWE

ECMU0060 pistons will work in old and new engines as they have for years. ECMU0276 pistons will NOT work in the old engines with bridged exhaust.

The rings, although visibly different (letters on the top surface), are interchangeable from piston to piston and model to model. The shape and material of the rings are equivalent. Wrist pins and “C” clips are also interchangeable.

New part numbers are as follows:

Description	Old Part Number	New Part Number for Venom
Piston kit	ECMU0060 (A, B, C etc...)	ECMU0276 (A, B, C etc..)



This is a factory production change for routine product improvement. This bulletin is for notification of modification only, not for warranty authorization.