



Technical Service Bulletin

Cobra Motorcycle Mfg.

240 Uran street
Hillsdale, MI 49242

(517) 437-9100 phone
(517) 437-9101 fax

November 21 2014

TSB0715 CX65 2012-1014 Frames

Going forward, the service replacement frame for a 2012 - 2014 CX65 (FAC62012) will be the 2015 (FAC62015). This will require the customer to upgrade Power Valve and Solenoid assemblies per TSB0616.